



AAA Service Advisory



Vehicle damage can occur from improper installation of tie down devices on the rear axle of Ram 1500 series pick-up trucks.

Concern: Possible damage to the wheel speed sensor and the wheel speed sensor wiring harness.

Vehicle: 2009 and 2010 model year Dodge, Ram 1500 series pickup trucks.





Diagram is courtesy of the Chrysler® Group, LLC

To avoid possible damage, use the correct tie down location and securing points as posted in the 2009 and 2010, AAA/CAA Towing and Service Manuals. T-hook tie down points are illustrated below:



If you have questions or comments regarding this advisory, please e-mail the AAA, Technical Training and Research Department at: RPST@national.aaa.com